
Multi-pin connectors at dash panel insert - Vehicles up to Model Year 1999

Note

With the exception of three, all warning lamps are fitted with LEDs. In the event of failure of a warning lamp with LED, the dash panel insert must be replaced.

Midline dash panel insert



1 - Main beam warning lamp

2 - TCS/ESP warning lamp

3 - Trailer turn signal warning lamp, only if trailer hitch fitted

A - 32-pin blue connector


B - 32-pin green connector

C - Cover panel for vehicles with no ambient temperature gauge

Note

The cover panel -C- must be removed if the dash panel insert is replaced on vehicles with ambient temperature gauge or on service installation of an ambient temperature gauge.

Highline dash panel insert



1 - Main beam warning lamp

2 - TCS/ESP warning lamp

3 - Trailer turn signal warning lamp, only if trailer hitch fitted

A - 32-pin blue connector

B - 32-pin green connector

C - 20-pin red connector